


Sensor back-mounted,
facing outwards

IS1 to be bent backwards
(facing up)



L/N tabs to be soldered underside,
trafo covering the solder lugs

25.4

25.4

25.4

19.05

12mm milled holes